

### SELLER'S PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between the Seller and any buyer. The Seller authorizes the Listing Broker in this transaction to disclose the information in this statement to other real estate licensees and to prospective buyers of this property. The Seller agrees to notify the Listing Broker promptly of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

**NOTE: DO NOT LEAVE ANY QUESTIONS BLANK, WRITE N/A (NOT APPLICABLE) OR UNKNOWN IF NEEDED.**

PROPERTY LOCATED AT: Lily Bay Road, Frenchtown, Me 04441

#### SECTION I. WATER SUPPLY

TYPE OF SYSTEM:  Public  Private  Seasonal \_\_\_\_\_  Unknown  
 Drilled  Dug  Other \_\_\_\_\_

MAJUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?  
Pump:  Yes  No  N/A Quantity: \_\_\_\_\_  Yes  No  Unknown  
Quality:  Yes  No  Unknown

If YES to any question, please explain in the comment section below or with attachment.  
WATER TEST: Have you had the water tested?  Yes  No  
If YES: Date of most recent test: 2004 Are test results available?  Yes  No  
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation?  Yes  No  
If YES, are test results available?  Yes  No  
What steps were taken to remedy the problem? \_\_\_\_\_

• IF PRIVATE:  
INSTALLATION: Location: Front of Cabin  
Installed BY: Rolfe Well Drilling DATE of Installation: 1998  
What is the source of your information: Doug Cross  
USE: Number of Persons currently using system? 5  
Does system supply water for more than one household?  Yes  No  Unknown

COMMENTS: \_\_\_\_\_

#### SECTION II. WASTE WATER DISPOSAL

TYPE OF SYSTEM:  Public  Private  Quasi-Public \_\_\_\_\_  Unknown

• IF PUBLIC OR QUASI-PUBLIC:  
Have you experienced any problems such as line or other malfunctions?  Yes  No  
What steps were taken to remedy the problem? \_\_\_\_\_

• IF PRIVATE:  
TANK:  Septic Tank  Holding Tank  Cesspool  Other: \_\_\_\_\_  
Tank Size:  500 Gal.  1000 Gal.  Unknown  Other: \_\_\_\_\_  
Tank Type:  Concrete  Metal  Unknown  Other: \_\_\_\_\_  
Location: Behind Cabin OR  Unknown Date of Installation: 1994  
Date of Last Servicing: 2006 Name of Company Servicing Tank: n/a  
Have you experienced any malfunctions?  Yes  No  
If yes, give the date and describe the problem: \_\_\_\_\_

LEACH FIELD: \_\_\_\_\_  Yes  No  Unknown

If YES: Location: Up by road 300 from camp  
Date of installation of leach field: March 22, 2008 Installed By: \_\_\_\_\_  
Date of Last Servicing: n/a Name of Service Company: \_\_\_\_\_  
Have you experienced any malfunctions?  Yes  No  
If yes, give the date and describe the problem & what steps were taken to remedy: \_\_\_\_\_

Does Seller have records of the septic system design indicating the number of bedrooms the system was designed for?  Yes  No  
If YES, is it available? yes

SOURCE OF INFORMATION: Doug Cross

COMMENTS: n/a

IS SYSTEM LOCATED IN A SHORELAND ZONE?  Yes  No  Unknown

July 2006 Page 1 of 3 - SPD Buyer(s) initials \_\_\_\_\_ Seller(s) initials DC

The Folsom Realty Group P.O. Box 512, Greenville ME 04441  
Phone: 2076953766 Fax: (207) 695-3605 fred@andloro Cross.zfx

PROPERTY LOCATED AT Lily Bay Road, Frenchtown, Me 04441

**SECTION III. HEATING SYSTEM(S)/SOURCE(S)**

Heating System(s)/Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	oil	wood		
Age of system(s)/source(s)	2000	2008		
Name of company that services system(s)/source(s)	A.E. Robinson			
Date of most recent service call	2007			
Annual consumption per system/ source (i.e., gallons, kilowatt hours, cord(s))	200 for the winter	n/a		
Malfunction per system(s)/ source(s) within past 2 years	no	no		
Other pertinent information				

Buried Oil Supply Line:  Yes  No  Unknown Sleved:  Yes  No  
 Chimney(s) Lined:  Yes  No  Unknown Age: 1998 Last Cleaned: n/a  
 Is more than one heat source vented through one flue?  Yes  No  Unknown  
 COMMENTS: \_\_\_\_\_

**SECTION IV. HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Current or previously existing:  
 Are there now, or have there ever been, any underground storage tanks on your property?  Yes  No  Unknown  
 IF YES: Are tanks in current use?  Yes  No  
 IF NO above: How long have tank(s) been out of service? \_\_\_\_\_  
 What materials are, or were, stored in the tank(s)? \_\_\_\_\_  
 Age of tank(s): \_\_\_\_\_ Size of tank(s): \_\_\_\_\_  
 Location: \_\_\_\_\_  
 Have you experienced any problems such as leakage? \_\_\_\_\_  
 Are tanks registered with the Dept. of Environmental Protection?  Yes  No  Unknown  
 If tanks are no longer in use, have tanks been abandoned according to D.E.P.?  Yes  No  Unknown  
 Comments: \_\_\_\_\_

B. ASBESTOS - Current or previously existing:  
 • as insulation on the heating system pipes or duct work?  Yes  No  Unknown  
 • in the siding?  Yes  No  Unknown • in the roofing shingles?  Yes  No  Unknown  
 • in flooring tiles?  Yes  No  Unknown • other: \_\_\_\_\_  Yes  No  Unknown  
 IF YES: Source of information: \_\_\_\_\_  
 COMMENTS: \_\_\_\_\_

C. RADON/AIR - Current or previously existing:  
 Has the property been tested?  Yes  No  Unknown  
 IF YES: Date: \_\_\_\_\_ By: \_\_\_\_\_  
 Results: \_\_\_\_\_ If applicable, What remedial steps were taken? \_\_\_\_\_  
 Has the property been tested since remedial steps?  Yes  No  Unknown  
 Are test results available?  Yes  No Results & Comments: \_\_\_\_\_

D. RADON/WATER - Current or previously existing:  
 Has the property been tested?  Yes  No  Unknown  
 IF YES: Date: \_\_\_\_\_ By: \_\_\_\_\_  
 Results: \_\_\_\_\_ If applicable, What remedial steps were taken? \_\_\_\_\_  
 Has the property been tested since remedial steps?  Yes  No  Unknown  
 Are test results available?  Yes  No Results & Comments: \_\_\_\_\_

E. LEAD-BASED PAINT/PAINT HAZARDS - Current or previously existing: (Note: Lead-based paint is most commonly found in homes constructed prior to 1978. See EPA Disclosure brochure form and Maine Lead Warning for more information)  
 Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?  Yes  No  Unknown  
 Unknown but possible due to age  
 IF YES, describe location and the basis for the determination: \_\_\_\_\_  
 Do you know of any records or reports pertaining to such lead-based paint or lead-based paint hazards:  Yes  No  
 IF YES, describe: \_\_\_\_\_  
 Are you aware of any cracking, peeling or flaking paint?  Yes  No  
 COMMENTS: no paint

July 2006 Page 2 of 3 - SPD Buyer(s) Initials \_\_\_\_\_ Seller(s) Initials DC

PROPERTY LOCATED AT Lily Bay Road, Frenchtown, Me 04441

F. OTHER HAZARDOUS MATERIALS - Current or previously existing:

- TOXIC MATERIAL:  Yes  No  Unknown
- LAND FILL:  Yes  No  Unknown
- RADIOACTIVE MATERIAL:  Yes  No  Unknown

OTHER: \_\_\_\_\_

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

**SECTION V. GENERAL INFORMATION**

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private road/homeowner associations or restrictive covenants?  Yes  No  Unknown

IF YES: Explain: Shared Drive Way

What is your source of information: Doug Cross

Are there any tax exemption or reduction for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?  Yes  No  Unknown

IF YES: Explain: \_\_\_\_\_

Leased Equipment (e.g., propane tank, hot water heater, satellite dish): Type: n/a

Age: Age of House: 10 yrs How long has Seller owned it: 10yrs

Roof: Age - Structure: 10 yrs Age - Shingles: 10 yrs

Moisture or leakage: no

Comments: \_\_\_\_\_

Foundation/Basement: Sump Pump:  Yes  No  Unknown Comments: \_\_\_\_\_

Moisture or leakage since you owned the property:  Yes  No  Unknown Comments: \_\_\_\_\_

Knowledge of prior moisture or leakage:  Yes  No  Unknown Comments: \_\_\_\_\_

Mold: Has the property ever been tested for mold?  Yes  No  Unknown If YES, are test results available?  Yes  No

Electrical:  Fuses  Circuit Breaker  Other: \_\_\_\_\_  Unknown

Has the property been surveyed?  Yes  No  Unknown If YES, is the survey available?  Yes  No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: n/a

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE:  Yes  No

**SECTION VI. ADDITIONAL INFORMATION**

Building was built by current owner.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Doug Cross

SELLER

3-23-08

DATE

SELLER

DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER

DATE

BUYER

DATE



Maine Association of REALTORS®/Copyright © July 2006. All Rights Reserved. Page 3 of 3 SPD

